

Minutes of Meeting

Subject: 5th Expert meeting

1. 11TH INSPECTION OF THE WAGON AND NOISE MEASUREMENT

- 11th inspection took place at Mělník Container Terminal.
- Inspections were done according inspection sheet and values were written in control and measurement sheet,
- Noise measurement was conducted with two wagons, one with brake blocks and one with DRFB discs.
- The results from noise measurement were saved in Extech HD600 Datalogging Sound Level Meter, and then exported to computer for final analysis.

2. DISCUSSION ON TESTING RESULTS AND OTHER MEASUREMENTS

2.1. Presentation of real environment test results

- Fifth expert meeting took place at Mělník Container Terminal. In the beginning of the meeting, introductory speech was done from side of project manager.
- Presentation of real environment test flow and results was done by ZX-Benet. Presentation in detailed described each inspection procedure and result of the same.
- Beside above mentioned, presentation of CALIPRI measuring equipment and measurement process of DRFB disc wear rate was done by ZX-Benet.

2.2. Discussion on test results

- During the meeting, discussion was on analysis of DRFB disc wear rate, and calculation of life cycle of DRFB disc against driven kilometers.
- Debate was on next steps needed for WP4 (fourth work package) within FUTURA project.

3. ANY OTHER BUSINESS

- Structure and content of deliverable D4.2 was discussed between ZX-Benet and Kavis.